

Appendix B - Street Conditions

Street Name	Section ID	Unique ID	Road ID Number	From	To	Neighborhood	Length (Ft)	PCI	Defects	OBJECTID	CLASS
Aberdeen Ave	1	CDSAD01	10100	Southern	28th W	West Latonia	627.0	Satisfactory	Alligator Cracking, Patching	3687	6
Alexandria	1	CDSAL01	10103	Madison	28th W	West Latonia	840.2	Satisfactory	Alligator Cracking, Potholes	2596	6
Ashland Ave	1	CDSAH01	10122	Madison	Southern	Latonia Terrace	1,696.8	Satisfactory	Rutting, Patching, Weathering	1910	6
Auburn Ave	1	CDSAB01	10977	Rosina	West End	West Latonia	220.7	Satisfactory	Joint Cracking, Weathering	2675	6
Baltimore Ave	3	CDSBT03	10836	Vermont	Glenn	Latonia Rosedale	122.6	Very Good	Alligator Cracking	3952	6
Baltimore Ave	2	CDSBT02	10839	Michigan	Vermont	Latonia Rosedale	283.6	Very Good	Utility Patching	3947	6
Baltimore Ave	1	CDSBT01	10838	East End	Michigan	Latonia Rosedale	146.2	Very Good	No Distress	3940	6
Beech Ave	1	CDSBH01	10036	34th	North End	West Latonia	1,124.4	Satisfactory	Alligator Cracking, Weathering	888	6
Beech Ave	1	CDSBH01	10034	34th	North End	West Latonia	137.9	Satisfactory	Alligator Cracking, Weathering	3468	6
Birch Ave	1	CDSBR01	10955	Madison	South End	West Latonia	582.4	Poor	Alligator Cracking, Weathering, Potholes	1438	6
Blackburn Rd	1	CDSBB01	10950	Rogers	Sehon	West Latonia	306.3	Poor	Weathering, Alligator Cracking, Patching	2300	6
Boron Dr	2	CDSBO02	9158	Howard Litzler	South End	West Latonia	779.7	Poor	Joint Cracking, Uneven Sections	3971	6
Boron Dr	1	CDSBO01	9183	43rd W	Howard Litzler	West Latonia	1,239.4	Good	Joint Cracking, Potholes, Alligator Cracking	3055	6
Carlisle Ave	2	CDSCS02	10149	35th W	South End	West Latonia	292.5	Good	Patching, Weathering	3708	6
Carlisle Ave	1	CDSCS01	10156	33rd W	35th W	West Latonia	409.2	Very Good	Weathering	1661	6
Caroline Ave	5	CDSCN05	10026	32nd W	31st W	West Latonia	257.0	Poor	Alligator Cracking, Patching, Weathering	701	6
Caroline Ave	6	CDSCN06	10019	31st W	North End	West Latonia	174.3	Poor	Alligator Cracking, Weathering	2411	6
Caroline Ave	4	CDSCN04	10018	33rd W	32nd W	West Latonia	258.5	Poor	Alligator Cracking, Patching, Potholes	2461	6
Caroline Ave	2	CDSCN02	10011	36th W	34th W	West Latonia	520.4	Poor	Alligator Cracking, Patching	2341	6
Caroline Ave	1	CDSCN01	10905	Southern	36th W	West Latonia	163.0	Good	Alligator Cracking	4194	6
Caroline Ave	1	CDSCN01	10897	Southern	36th W	West Latonia	59.8	Good	Alligator Cracking	4195	6
Caroline Ave	1	CDSCN01	10908	Southern	36th W	West Latonia	123.3	Good	Alligator Cracking	3405	6
Caroline Ave	1	CDSCN01	10892	Southern	36th W	West Latonia	85.3	Good	Alligator Cracking	3408	6
Caroline Ave	1	CDSCN01	10907	Southern	36th W	West Latonia	51.4	Good	Alligator Cracking	3845	6
Caroline Ave	1	CDSCN01	10898	Southern	36th W	West Latonia	36.0	Good	Alligator Cracking	4142	6
Caroline Ave	1	CDSCN01	10901	Southern	36th W	West Latonia	137.2	Good	Alligator Cracking	4160	6
Caroline Ave	3	CDSCN03	10010	34th W	33rd W	West Latonia	261.0	Satisfactory	Weathering	3788	6
Carroll St	1	CDSCR01	10835	45th E	South End	Latonia Rosedale	978.3	Satisfactory	Block Cracking	4298	6
Church St	9	CDSCH09	9955	41st E	42nd E	West Latonia	326.6	Poor	Alligator & Block Cracking, Utility Patching	3344	6
Church St	11	CDSCH11	9950	43rd E	City Line	West Latonia	240.0	Poor	Alligator Cracking, Depressions, Patching	5292	6
Church St	7	CDSCH07	9940	39th E	40th E	Ritte's East Latonia	525.1	Poor	Utility Patching, Alligator & Block Cracking	3917	6
Church St	3	CDSCH03	9956	35th E	36th E	Ritte's East Latonia	460.5	Poor	Potholes, Alligator Cracking, Patching	3483	6
Church St	10	CDSCH10	9949	42nd E	43rd E	West Latonia	332.3	Poor	Patching, Block & Alligator Cracking	3564	6
Church St	4	CDSCH04	9958	36th E	Southern	Ritte's East Latonia	459.8	Poor	Alligator Cracking, Patching, Potholes	4311	6
Church St	6	CDSCH06	9945	Decoursey	39th E	Ritte's East Latonia	434.5	Good	Weathering, Utility Patching, Alligator Cracking	2685	6
Church St	5	CDSCH05	9954	Southern	Decoursey	Ritte's East Latonia	346.5	Good	Alligator Cracking, Utility Patching	1532	6
Church St	8	CDSCH08	9947	40th E	41st E	West Latonia	332.0	Good	Utility Patching, Weathering	3961	6
Church St	1	CDSCH01	9982	33rd E	Daniels	Latonia Milldale	241.8	Satisfactory	Alligator Cracking	2463	6
Church St	2	CDSCH02	9973	Daniels	35th E	Latonia Milldale	410.8	Very Good	Alligator Cracking	3721	6
Clifford Ave	1	CDSCF01	10051	Southern	Indiana	West Latonia	1,128.6	Poor	Alligator Cracking, Weathering, Block Cracking	3485	6
Clifton Ave	2	CDSCLO2	9782	Rosedale	46th E	West Latonia	248.2	Very Good	Utility Patching	3815	6
Clifton Ave	1	CDSCLO1	9778	45th E	Rosedale	West Latonia	391.8	Very Good	No Distress	2448	6
Cottage Ave	1	CDSCT01	10165	33rd W	South End	West Latonia	299.4	Good	Alligator Cracking, Potholes, Weathering	3641	6
Dakota	1	CDSDK01	10108	Madison	28th St	West Latonia	858.9	Good	Alligator Cracking, Weathering, Potholes	3874	6
Daniel Goodenough	1	CDSDG01	10037	Clifford	Beech	West Latonia	344.5	Good	Alligator Cracking, Weathering	3469	6
Daniels St	1	CDSDN01	9965	East End	Lincoln	Latonia Milldale	298.1	Poor	Rutting, Patching, Alligator Cracking	3776	6
Daniels St	2	CDSDN02	9966	Lincoln	Church	Latonia Milldale	186.6	Poor	Alligator Cracking, Potholes, Patching	343	6
Daniels St	2	CDSDN02	9967	Lincoln	Church	Latonia Milldale	186.2	Poor	Alligator Cracking, Potholes, Patching	3773	6
Daniels St	3	CDSDN03	9981	Church	Decoursey	Latonia Milldale	376.9	Satisfactory	Alligator Cracking	2464	6
Decoursey Ave	1	CSDSC01	10948	Madison	28th	Latonia Milldale	310.1	Poor	Weathering, Alligator Cracking	2034	6

Street Name	Section ID	Unique ID	Road ID Number	From	To	Neighborhood	Length (Ft)	PCI	Defects	OBJECTID	CLASS
Decoursey Ave	3	CSDSDC03	10941	29th E	30th E		358.0	Satisfactory	Weathering	961	6
Decoursey Ave	2	CSDSDC02	10944	28th E	29th E	Latonia Milldale	234.0	Satisfactory	Weathering	1427	6
E 28th St	6	CDS2806	10943	Decoursey	East End	Latonia Milldale	454.1	Good	Weathering, Patching, Alligator Cracking	2033	6
E 29th St	2	CDS2902	10936	Decoursey	East End	Latonia Milldale	323.1	Satisfactory	Weathering	1426	6
E 31st St	4	CDS3104	10930	Frazier	East End	Latonia Milldale	648.6	Good	Alligator Cracking, Potholes	235	6
E 31st St	3	CDS3103	10932	Decoursey	Frazier	Latonia Milldale	406.2	Good	Alligator Cracking, Patching	1443	6
E 32nd St	8	CDS3208	10914	Frazier	East End	Latonia Milldale	317.6	Good	Block Cracking, Patching	1442	6
E 32nd St	7	CDS3207	10925	Decoursey	Frazier	Latonia Milldale	73.3	Satisfactory	Patching, Weathering	3701	6
E 32nd St	7	CDS3207	10922	Decoursey	Frazier	Latonia Milldale	520.4	Satisfactory	Patching, Weathering	3278	6
E 33rd St	14	CDS3314	10913	Winchester	East End	Latonia Milldale	474.0	Poor	Alligator Cracking, Patching	2641	6
E 33rd St	12	CDS3312	9996	Church	Frazier	Latonia Milldale	369.2	Poor	Alligator Cracking, Potholes, Patching	2165	6
E 33rd St	13	CDS3313	10912	Frazier	Winchester	Latonia Milldale	321.9	Good	Weathering, Alligator Cracking	3075	6
E 33rd St	13	CDS3313	10916	Frazier	Winchester	Latonia Milldale	141.5	Good	Weathering, Alligator Cracking	3263	6
E 34th St	5	CDS3405	10919	Winchester	East End	Latonia Milldale	166.3	Good	Alligator Cracking, Weathering	4023	6
E 35th St	11	CDS3511	9961	Church	Lincoln	Latonia Milldale	188.1	Satisfactory	Alligator Cracking, Patching, Weathering	2922	6
E 35th St	11	CDS3511	9962	Church	Lincoln	Latonia Milldale	185.2	Satisfactory	Alligator Cracking, Patching, Weathering	2925	6
E 35th St	10	CDS3510	9972	Decoursey	Church	Latonia Milldale	375.8	Very Good	Alligator Cracking,	3722	6
E 36th St	2	CDS3602	9957	Lincoln	Church	Ritte's East Latonia	189.7	Good	Alligator Cracking, Weathering	653	6
E 36th St	2	CDS3602	9924	Lincoln	Church	Ritte's East Latonia	185.2	Good	Alligator Cracking, Weathering	655	6
E 36th St	1	CDS3601	9917	Park	Lincoln	Ritte's East Latonia	383.1	Good	Alligator Cracking, Patching, Weathering	659	6
E 36th St	3	CDS3603	9970	Church	Decoursey	Ritte's East Latonia	186.6	Very Good	Patching, Weathering	3482	6
E 36th St	3	CDS3603	9964	Church	Decoursey	Ritte's East Latonia	187.5	Very Good	Patching, Weathering	3484	6
E 38th St	8	CDS3808	13482	Tracy	Leslie	Ritte's East Latonia	249.9	Good	Block Cracking, Utility Patching	230	6
E 38th St	5	CDS3805	9923	Church	Lincoln	Ritte's East Latonia	289.6	Good	Utility Patching, Alligator Cracking	1986	6
E 38th St	9	CDS3809	9879	Leslie	East End	Ritte's East Latonia	132.5	Good	Weathering, Block Cracking	4450	6
E 38th St	7	CDS3807	9855	Glenn	East End	Ritte's East Latonia	257.7	Satisfactory	Edge Cracking, Weathering	4448	6
E 38th St	4	CDS3804	10198	Locke	Church	Ritte's East Latonia	69.6	Satisfactory	Utility Patching, Alligator Cracking	2908	6
E 38th St	4	CDS3804	10196	Locke	Church	Ritte's East Latonia	71.9	Satisfactory	Utility Patching, Alligator Cracking	2909	6
E 38th St	4	CDS3804	10197	Locke	Church	Ritte's East Latonia	234.7	Satisfactory	Utility Patching, Alligator Cracking	2911	6
E 38th St	3	CDS3803	10195	Winston	Locke	Ritte's East Latonia	152.2	Satisfactory	Alligator Cracking	341	6
E 38th St	6	CDS3806	9914	Lincoln	Park	Ritte's East Latonia	396.5	Satisfactory	Joint Cracking, Patching, Alligator Cracking	1989	6
E 39th St	3	CDS3903	9932	Church	Lincoln	Ritte's East Latonia	375.8	Good	Alligator Cracking	3676	6
E 39th St	4	CDS3904	9929	Lincoln	Decoursey	Ritte's East Latonia	125.0	Satisfactory	Alligator Cracking	2768	6
E 39th St	5	CDS3905	9936	Decoursey	Park	Ritte's East Latonia	95.5	Satisfactory	Alligator Cracking, Utility Patching	2770	6
E 39th St	5	CDS3905	9935	Decoursey	Park	Ritte's East Latonia	186.8	Satisfactory	Alligator Cracking, Utility Patching	2773	6
E 39th St	6	CDS3906	9891	Park	Huntington	Ritte's East Latonia	279.4	Satisfactory	Alligator Cracking	3629	6
E 39th St	6	CDS3906	9893	Park	Huntington	Ritte's East Latonia	153.0	Satisfactory	Alligator Cracking	3640	6
E 39th St	1	CDS3901	10190	Winston	Locke	Ritte's East Latonia	331.4	Satisfactory	Alligator Cracking, Weathering	3671	6
E 39th St	2	CDS3902	9948	Locke	Church	Ritte's East Latonia	207.2	Satisfactory	Utility Patching, Alligator Cracking	3672	6
E 39th St	2	CDS3902	9937	Locke	Church	Ritte's East Latonia	168.0	Satisfactory	Utility Patching, Alligator Cracking	3673	6
E 40th St	5	CDS4005	9871	Decoursey	Huntington	Ritte's East Latonia	233.1	Poor	Alligator Cracking, Utility Patching	3819	6
E 40th St	5	CDS4005	9864	Decoursey	Huntington	Ritte's East Latonia	85.9	Poor	Alligator Cracking, Utility Patching	3822	6
E 40th St	5	CDS4005	9858	Decoursey	Huntington	Ritte's East Latonia	195.4	Poor	Alligator Cracking, Utility Patching	3927	6
E 40th St	5	CDS4005	9884	Decoursey	Huntington	Ritte's East Latonia	73.7	Poor	Alligator Cracking, Utility Patching	3127	6
E 40th St	5	CDS4005	9897	Decoursey	Huntington	Ritte's East Latonia	107.5	Poor	Alligator Cracking, Utility Patching	3331	6
E 40th St	2	CDS4002	9946	Locke	Church	Ritte's East Latonia	377.7	Good	Weathering, Alligator Cracking	3918	6
E 40th St	1	CDS4001	10188	Winston	Locke	Ritte's East Latonia	506.8	Good	Weathering, Alligator Cracking	2155	6
E 40th St	3	CDS4003	9939	Church	Lincoln	Ritte's East Latonia	383.2	Satisfactory	Alligator Cracking, Utility Patching	3817	6
E 40th St	4	CDS4004	9930	Lincoln	Decoursey	Ritte's East Latonia	308.4	Satisfactory	Alligator Cracking, Utility Patching	3332	6
E 40th St	6	CDS4006	9845	Huntington	Glenn	Ritte's East Latonia	327.3	Satisfactory	Joint Cracking	3338	6

Street Name	Section ID	Unique ID	Road ID Number	From	To	Neighborhood	Length (Ft)	PCI	Defects	OBJECTID	CLASS
E 41st St	1	CDS4101	10186	Winston	Church	West Latonia	982.4	Good	Alligator Cracking, Utility Patching	4145	6
E 41st St	2	CDS4102	9942	Church	Decoursey	West Latonia	924.9	Good	Alligator Cracking, Weathering, Patching	1957	6
E 41st St	3	CDS4103	9867	Decoursey	Huntington	Latonia Rosedale	185.4	Very Good	No Distress	4147	6
E 41st St	3	CDS4103	9840	Decoursey	Huntington	Latonia Rosedale	553.9	Very Good	No Distress	3958	6
E 42nd St	2	CDS4202	9952	Church	Decoursey	West Latonia	1,167.2	Very Poor	Alligator Cracking, Patching, Heaving	4461	6
E 42nd St	1	CDS4201	10184	Winston	Church	West Latonia	1,079.5	Good	Utility Patching, Block Cracking, Weathering	3345	6
E 42nd St	3	CDS4203	9831	Decoursey	McKee	Latonia Rosedale	183.7	Very Good	No Distress	3341	6
E 42nd St	4	CDS4204	9827	McKee	Huntington	Latonia Rosedale	181.6	Very Good	No Distress	4150	6
E 42nd St	3	CDS4203	9842	Decoursey	McKee	Latonia Rosedale	288.1	Very Good	No Distress	4625	6
E 43rd St	3	CDS4303	10870	Winston	Church	West Latonia	1,179.6	Poor	Alligator Cracking, Utility Patching, Weathering	3565	6
E 43rd St	5	CDS4305	9812	Decoursey	McKee	Latonia Rosedale	196.8	Good	Alligator Cracking, Weathering	4175	6
E 43rd St	5	CDS4305	9811	Decoursey	McKee	Latonia Rosedale	186.1	Good	Alligator Cracking, Weathering	4177	6
E 43rd St	7	CDS4307	9835	Glenn	Vermont	Latonia Rosedale	300.2	Good	Weathering, Alligator Cracking	3087	6
E 43rd St	8	CDS4308	9851	Vermont	Michigan	Latonia Rosedale	268.3	Good	Alligator Cracking, Utility Patching, Weathering	3084	6
E 43rd St	6	CDS4306	9820	McKee	Huntington	Latonia Rosedale	179.9	Satisfactory	Alligator Cracking, Utility Patching	4633	6
E 43rd St	4	CDS4304	9951	Church	Decoursey	West Latonia	1,054.8	Very Good	Block Cracking, Utility Patching	2469	6
E 43rd St	4	CDS4304	9819	Church	Decoursey	West Latonia	363.1	Very Good	Block Cracking, Utility Patching	4186	6
E 44th St	2	CDS4402	9796	McKee	Huntington	Latonia Rosedale	161.3	Poor	Alligator Cracking	7227	6
E 44th St	4	CDS4404	9856	Vermont	Michigan	Latonia Rosedale	266.6	Good	Alligator Cracking	4783	6
E 44th St	1	CDS4401	9797	Decoursey	McKee	Latonia Rosedale	21.3	Satisfactory	Alligator Cracking	3580	6
E 44th St	1	CDS4401	9798	Decoursey	McKee	Latonia Rosedale	201.8	Satisfactory	Alligator Cracking	6828	6
E 44th St	3	CDS4403	9813	Glenn	Vermont	Latonia Rosedale	127.9	Very Good	No Distress	4788	6
E 45th St	4	CDS4504	10844	Caroll	Virginia	Latonia Rosedale	659.4	Satisfactory	Block Cracking	2788	6
E 45th St	3	CDS4503	10843	Glenn	Carroll	Latonia Rosedale	361.8	Satisfactory	Block Cracking	4285	6
E 45th St	5	CDS4505	10840	Virginia	East End	Latonia Rosedale	277.5	Very Good	Block Cracking	3092	6
E 45th St	1	CDS4501	9779	Clifton	Decoursey	West Latonia	241.7	Very Good	Alligator Cracking	7312	6
E 45th St	2	CDS4502	9792	Decoursey	Huntington	Latonia Rosedale	159.4	Very Good	No Distress	1896	6
E 45th St	2	CDS4502	9787	Decoursey	Huntington	Latonia Rosedale	152.9	Very Good	No Distress	2475	6
E 46th St	1	CDS4601	9781	Victory	Clifton	West Latonia	503.6	Good	Utility Patching, Alligator Cracking, Weathering	3816	6
E 46th St	2	CDS4602	9772	Clifton	Decoursey	West Latonia	260.9	Good	Utility Patching, Alligator Cracking, Weathering	4156	6
E 46th St	4	CDS4604	9776	Huntington	East End	Latonia Rosedale	209.9	Very Good	Weathering	3954	6
E 46th St	3	CDS4603	9783	Decoursey	Huntington	Latonia Rosedale	257.7	Very Good	Alligator Cracking	4297	6
E 47th St	1	CDS4701	9764	West End	Decoursey	West Latonia	260.4	Satisfactory	Utility Patching	4893	6
E 47th St	2	CDS4702	9766	Decoursey	Huntington	Latonia Rosedale	68.6	Satisfactory	Block Cracking	4895	6
E 47th St	2	CDS4702	9769	Decoursey	Huntington	Latonia Rosedale	126.3	Satisfactory	Block Cracking	4899	6
E 47th St	3	CDS4703	9785	Huntington	Eureka	Latonia Rosedale	134.3	Very Good	Block Cracking	4902	6
E 47th St	3	CDS4703	9794	Huntington	Eureka	Latonia Rosedale	108.2	Very Good	Block Cracking	4907	6
E 47th St	4	CDS4704	9802	Eureka	East End	Latonia Rosedale	102.8	Very Good	No Distress	4673	6
E Park Dr	3	CDSPD03	9905	Park Dr	East End	Ritte's East Latonia	144.0	Poor	Alligator Cracking, Weathering	3738	6
E Southern Ave	9	CDSSN09	9963	Decoursey	Church	West Latonia	190.5	Poor	Alligator Cracking, Patching, Weathering	4313	6
E Southern Ave	9	CDSSN09	9971	Decoursey	Church	West Latonia	170.9	Poor	Alligator Cracking, Patching, Weathering	4317	6
E Southern Ave	9	CDSSN09	9983	Decoursey	Church	West Latonia	25.8	Poor	Alligator Cracking, Patching, Weathering	4318	3
E Southern Ave	10	CDSSN10	9921	Church	Lincoln	West Latonia	187.7	Good	Joint Cracking, Weathering	2518	6
E Southern Ave	10	CDSSN10	9953	Church	Lincoln	West Latonia	187.4	Good	Joint Cracking, Weathering	4310	6
E Southern Ave	13	CDSSN13	9885	Huntington	Glenn	Ritte's East Latonia	351.5	Good	Alligator Cracking, Patching	3631	6
E Southern Ave	11	CDSSN11	9908	Lincoln	Park	West Latonia	385.9	Good	Alligator Cracking, Weathering,	3634	6
E Southern Ave	12	CDSSN12	9895	Park	Huntington	Ritte's East Latonia	189.8	Good	Alligator Cracking, Weathering	2654	6
E Southern Ave	14	CDSSN14	9886	Glenn	Myrtle	Ritte's East Latonia	316.5	Satisfactory	Weathering, Patching	1918	6
E Southern Ave	15	CDSSN15	9878	Myrtle	East End	Ritte's East Latonia	653.3	Satisfactory	Alligator Cracking, Patching, Weathering	2694	6
Earle Ave	2	CDSER02	9869	Gilbert	Tracy	Ritte's East Latonia	251.4	Good	Alligator Cracking, Patching	3709	6

Street Name	Section ID	Unique ID	Road ID Number	From	To	Neighborhood	Length (Ft)	PCI	Defects	OBJECTID	CLASS
Earle Ave	1	CDSER01	9861	Glenn	Gilbert	Ritte's East Latonia	247.9	Good	Weathering, Alligator Cracking, Dip	2697	6
Earle Ave	3	CDSER03	9887	Tracy	Leslie	Ritte's East Latonia	250.7	Satisfactory	Alligator Cracking	3704	6
Ehmet Dr	1	CDSEH01	9788	Huntington	Eureka	Latonia Rosedale	108.6	Satisfactory	Block Cracking	3982	6
Ehmet Dr	1	CDSEH01	9793	Huntington	Eureka	Latonia Rosedale	131.2	Satisfactory	Block Cracking	4507	6
Elmwood St	1	CDSEW01	9803	Decoursey	McKee	Latonia Rosedale	135.4	Very Good	Edge Cracking	4590	6
Elmwood St	1	CDSEW01	9805	Decoursey	McKee	Latonia Rosedale	129.1	Very Good	Edge Cracking	3542	6
Elmwood St	2	CDSEW02	9825	Glenn	Vermont	Latonia Rosedale	217.3	Very Good	No Distress	4188	6
Emerson Ave	1	CDSEM01	10162	33rd W	35th W	West Latonia	410.6	Very Good	Patching	3678	6
Eugenia Ave	1	CDSEG01	10038	Southern	35th W	West Latonia	387.2	Good	Block Cracking, Potholes, Alligator Cracking	4214	6
Eureka St	1	CDSEK01	9789	Ehmet Dr	47th E	Latonia Rosedale	268.1	Satisfactory	Block Cracking	4906	6
Frazier	4	CDSFZ04	10928	31st E	30th E	Latonia Milldale	238.4	Poor	Alligator Cracking, Potholes, Weathering	236	6
Frazier	3	CDSFZ03	10929	32nd E	31st E	Latonia Milldale	259.0	Poor	Alligator Cracking, Potholes	3702	6
Frazier	2	CDSFZ02	10004	33rd E	32nd E	Westside	195.0	Good	Alligator Cracking, Potholes	3076	6
Frazier	2	CDSFZ02	10915	33rd E	32nd E	Westside	178.0	Good	Alligator Cracking, Potholes	3506	6
Frazier	1	CDSFZ01	9987	South End	33rd E	Westside	245.4	Good	Edge Cracking, Alligator Cracking, Weathering	2172	6
Gilbert Ave	1	CDSGB01	9853	Earle	South End	Latonia Milldale	374.0	Very Good	Depressions	2158	6
Glenn Ave	10	CDSGL10	10837	Baltimore	45th E	Latonia Rosedale	242.4	Good	Alligator Cracking, Potholes	2620	6
Glenn Ave	9	CDSGL09	9816	Elmwood	44th E	Latonia Rosedale	347.7	Satisfactory	Alligator Cracking	4789	6
Glenn Ave	8	CDSGL08	9810	43rd E	Elmwood	Ritte's East Latonia	341.8	Very Good	Alligator Cracking, Utility Patching	4581	6
Glenn Ave	8	CDSGL08	9824	43rd E	Elmwood	Ritte's East Latonia	90.5	Very Good	Alligator Cracking, Utility Patching	3347	6
Glenn Ave	6	CDSGL06	9852	Earle	40th E	Ritte's East Latonia	338.3	Very Good	Block Cracking	2618	6
Glenn Ave	3	CDSGL03	9881	Grant	Southern	Ritte's East Latonia	349.6	Very Good	Weathering	2425	6
Glenn Ave	1	CDSGL01	9890	North End	Windsor	West Latonia	265.4	Very Good	Weathering	3667	6
Glenn Ave	6	CDSGL06	9849	Earle	40th E	Ritte's East Latonia	112.7	Very Good	Block Cracking	3335	6
Glenn Ave	5	CDSGL05	9862	38th E	Earle	Ritte's East Latonia	539.1	Very Good	No Distress	2698	6
Glenn Ave	7	CDSGL07	9834	40th E	43rd E	Ritte's East Latonia	199.0	Very Good	No Distress	3088	6
Glenn Ave	7	CDSGL07	9844	40th E	43rd E	Ritte's East Latonia	484.1	Very Good	No Distress	4149	6
Glenn Ave	2	CDSGL02	9896	Winsor	Grant	West Latonia	223.9	Very Good	No Distress	3735	6
Glenn Ave	4	CDSGL04	9874	Southern	38th E	Ritte's East Latonia	556.1	Very Good	No Distress	7307	6
Grace St	1	CDSGC01	10046	Southern	35th W	Latonia Milldale	151.2	Satisfactory	Patching, Weathering	3097	6
Grace St	1	CDSGC01	10047	Southern	35th W	Latonia Milldale	412.8	Satisfactory	Patching, Weathering	4040	6
Graff St	3	CDSGF03	10031	34th W	35th W	West Latonia	259.0	Good	Weathering, Patching	3538	6
Graff St	2	CDSGF02	10028	33rd W	34th W	West Latonia	258.7	Very Good	Weathering	2440	6
Graff St	1	CDSGF01	10020	32nd W	33rd W	Ritte's East Latonia	254.2	Very Good	Weathering	3661	6
Grant Ct	1	CDSGT01	9894	Park	Glenn	Latonia Rosedale	453.1	Very Good	Alligator Cracking, Patching	2342	6
Harold Mason	2	CDSHM02	9998	Fraizer	East End	Ritte's East Latonia	263.9	Serious	Potholes, Unpaved sections	3505	6
Harold Mason	1	CDSHM01	10003	Union	Fraizer	Latonia Rosedale	487.3	Satisfactory	Alligator Cracking, Weathering	1454	6
Hazel Ave	1	CDSHZ01	10979	Rosina	West End	Latonia Rosedale	212.9	Satisfactory	Weathering	2644	6
Huntington Ave	7	CDSHT07	9800	44th E	45th E	Latonia Rosedale	817.5	Very Good	Block Cracking	1974	6
Huntington Ave	4	CDSHT04	9826	41st E	42nd E	Ritte's East Latonia	303.1	Very Good	Utility Patching	3057	6
Huntington Ave	5	CDSHT05	9817	42nd E	43rd E	Latonia Rosedale	318.3	Very Good	Block Cracking	3349	6
Huntington Ave	3	CDSHT03	9839	40th E	41st E	Ritte's East Latonia	321.9	Very Good	Alligator Cracking	3895	6
Huntington Ave	2	CDSHT02	9882	39th E	40th E	Latonia Milldale	187.2	Very Good	No Distress	2699	6
Huntington Ave	2	CDSHT02	9863	39th E	40th E	Latonia Milldale	54.1	Very Good	No Distress	2702	6
Huntington Ave	2	CDSHT02	9857	39th E	40th E	Latonia Milldale	127.9	Very Good	No Distress	3924	6
Huntington Ave	6	CDSHT06	9809	43rd E	44th E	Latonia Rosedale	685.2	Very Good	No Distress	4795	6
Huntington Ave	1	CDSHT01	9876	Southern	39th E	Latonia Milldale	926.6	Very Good	No Distress	3630	6
Huntington Ave	2	CDSHT02	9872	39th E	40th E	Latonia Milldale	179.1	Very Good	No Distress	3911	6
Huntington Ave	8	CDSHT08	9791	45th E	46th E	Latonia Rosedale	612.7	Very Good	No Distress	4296	6
Huntington Ave	9	CDSHT09	9777	46th E	47th E	Latonia Rosedale	134.0	Very Good	No Distress	4503	6

Street Name	Section ID	Unique ID	Road ID Number	From	To	Neighborhood	Length (Ft)	PCI	Defects	OBJECTID	CLASS
Huntington Ave	9	CDSHT09	9786	46th E	47th E	Latonia Rosedale	273.5	Very Good	No Distress	4898	6
Indiana Ave	1	CDSIN01	10041	Madison	Clifford	Latonia Rosedale	1,011.2	Poor	Alligator Cracking, Potholes, Patching	1969	6
Inez Ave	1	CDSIZ01	9994	Decoursey	Caroline	West Latonia	188.1	Satisfactory	Weathering	2226	6
Inez Ave	1	CDSIZ01	10891	Decoursey	Caroline	West Latonia	180.3	Satisfactory	Weathering	3844	6
Iowa Ave	1	CDSIW01	10043	Madison	South End	West Latonia	576.4	Very Good	Weathering	3501	6
Latonia Ave	1	CDSLTO1	10104	Madison	28th W	Ritte's East Latonia	862.3	Good	Patching, Alligator Cracking	2664	6
Latonia Ave	2	CDSLTO2	10101	28th W	Southern	Ritte's East Latonia	208.5	Satisfactory	Alligator Cracking, Weathering	7294	6
Latonia Ave	2	CDSLTO2	10098	28th W	Southern	Ritte's East Latonia	199.0	Satisfactory	Alligator Cracking, Weathering	7295	6
Latonia Ave	4	CDSLTO4	10089	32nd W	33rd W	West Latonia	406.1	Satisfactory	Weathering, Alligator Cracking	4439	6
Latonia Ave	5	CDSLTO5	10087	33rd W	35th W	West Latonia	411.0	Satisfactory	Patching, Alligator Cracking	3669	6
Latonia Ave	3	CDSLTO3	10094	Southern	32nd W	Ritte's East Latonia	417.5	Satisfactory	Patching, Alligator Cracking	4138	6
Latonia Ave	6	CDSLTO6	10085	35th W	City Line	West Latonia	513.0	Satisfactory	Weathering	1659	6
Leslie Ave	2	CDSL02	9880	Earle	38th E	Ritte's East Latonia	354.1	Very Good	Joint Cracking	3642	6
Leslie Ave	1	CDSL01	9875	South End	Earle	Ritte's East Latonia	432.7	Very Good	Block Cracking	3913	6
Lincoln Ave	6	CDSLNO6	9928	Decoursey	39th E	Ritte's East Latonia	172.2	Poor	Alligator Cracking, Weathering	3675	6
Lincoln Ave	5	CDSLNO5	9922	38th E	Decoursey	Ritte's East Latonia	264.1	Poor	Alligator Cracking, Utility Patching	231	6
Lincoln Ave	2	CDSLNO2	9925	35th E	36th E	Ritte's East Latonia	460.8	Poor	Potholes, Alligator Cracking	654	6
Lincoln Ave	3	CDSLNO3	9916	36th E	Southern	Ritte's East Latonia	437.4	Poor	Alligator Cracking, Weathering	3635	6
Lincoln Ave	1	CDSLNO1	9968	Daniels	35th E	West Latonia	409.6	Good	Alligator Cracking, Potholes	2924	6
Lincoln Ave	4	CDSLNO4	9915	Southern	38th E	Latonia Milldale	427.9	Good	Alligator Cracking, Utility Patching, Weathering	1982	6
Lincoln Ave	7	CDSLNO7	9931	39th E	40th E	Ritte's East Latonia	563.7	Good	Alligator Cracking, Weathering	3929	6
Locke St	2	CDSLK02	10205	39th E	38th E	West Latonia	161.7	Good	Alligator Cracking, Weathering, Patching	1664	6
Locke St	2	CDSLK02	10201	39th E	38th E	West Latonia	110.4	Good	Alligator Cracking, Weathering, Patching	3670	6
Locke St	2	CDSLK02	10199	39th E	38th E	West Latonia	164.3	Good	Alligator Cracking, Weathering, Patching	4452	6
Locke St	1	CDSLK01	9943	40th E	39th E	West Latonia	487.8	Satisfactory	Alligator Cracking, Weathering	3914	6
Mabel Ave	1	CDSMB01	10062	Southern	33rd	West Latonia	369.9	Satisfactory	Patching, Weathering	2715	6
Mabel Ave	2	CDSMB02	10063	33rd	35th	West Latonia	413.0	Satisfactory	Alligator Cracking, Weathering	1915	6
McKee St	2	CDSMK02	9815	43rd E	Elmwood	Latonia Rosedale	384.2	Very Good	No Distress	4589	6
McKee St	1	CDSMK01	9822	42nd E	43rd E	West Latonia	155.4	Very Good	No Distress	2781	6
McKee St	3	CDSMK03	9807	Elmwood	44th E	Latonia Rosedale	290.2	Very Good	No Distress	3967	6
McKee St	1	CDSMK01	9829	42nd E	43rd E	West Latonia	163.3	Very Good	No Distress	4634	6
Melton Ave	1	CDSMT01	10135	28th W	North End	Latonia Rosedale	302.8	Good	Alligator Cracking	3861	6
Michigan Ave	2	CDSMH02	10842	44th E	Baltimore	West Latonia	434.5	Satisfactory	Alligator Cracking	3941	6
Michigan Ave	1	CDSMH01	9860	43rd E	44th E	West Latonia	775.2	Very Good	Utility Patching, Dips	4779	6
Myrtle Ave	2	CDSMY02	10866	Park	Summit		106.5	Satisfactory	Patch, Weathering	2209	6
Myrtle Ave	1	CDSMY01	9899	Southern	Park	Latonia Rosedale	372.9	Satisfactory	Weathering, Patching	3406	6
Myrtle Ave	2	CDSMY02	9910	Park	Summit		272.4	Satisfactory	Patch, Weathering	3731	6
Park Ave	1	CDSPK01	9898	40th E	39th E	Ritte's East Latonia	403.9	Poor	Alligator Cracking, Utility Patching	3125	6
Park Ave	1	CDSPK01	9877	40th E	39th E	Ritte's East Latonia	184.5	Poor	Alligator Cracking, Utility Patching	3128	6
Park Ave	5	CDSPK05	9901	36th E	North End	Ritte's East Latonia	231.7	Very Good	Alligator Cracking	658	6
Park Ave	2	CDSPK02	9902	39th E	38th E	Ritte's East Latonia	281.8	Very Good	Alligator Cracking, Utility Patching	1656	6
Park Ave	3	CDSPK03	9911	38th E	Southern	Ritte's East Latonia	453.1	Very Good	Utility Patching	1988	6
Park Ave	2	CDSPK02	9912	39th E	38th E	Ritte's East Latonia	153.6	Very Good	Alligator Cracking, Utility Patching	2772	6
Park Ave	4	CDSPK04	9907	Southern	36th E	Ritte's East Latonia	140.8	Very Good	No Distress	2343	6
Park Ave	4	CDSPK04	9889	Southern	36th E	Ritte's East Latonia	272.8	Very Good	No Distress	2655	6
Park Dr	1	CDSPO1	9913	Myrtle	Park E	West Latonia	307.9	Good	Alligator Cracking, Weathering	3737	6
Park Dr	2	CDSPO2	9904	Park E	North End	Ritte's East Latonia	355.8	Good	Alligator Cracking, Block Cracking	7306	6
Rogers St	7	CDSRG07	10006	34th W	RR Tracks	West Latonia	134.3	Poor	Alligator Cracking, Weathering, Patching	2927	6
Rogers St	1	CDSRG01	10952	Madison	28th W	Ritte's East Latonia	235.4	Satisfactory	Alligator Cracking, Utility Patching	295	6
Rogers St	2	CDSRG02	10050	28th W	29th W	Ritte's East Latonia	249.6	Satisfactory	Alligator Cracking, Utility Patching	1437	6

Street Name	Section ID	Unique ID	Road ID Number	From	To	Neighborhood	Length (Ft)	PCI	Defects	OBJECTID	CLASS
Rogers St	1	CDSRG01	10949	Madison	28th W	Ritte's East Latonia	192.8	Satisfactory	Alligator Cracking, Utility Patching	2301	6
Rogers St	4	CDSRG04	10024	31st W	32nd W	West Latonia	254.4	Satisfactory	Alligator Cracking, Utility Patching	3466	6
Rogers St	5	CDSRG05	10015	32nd W	33rd W		260.7	Satisfactory	Alligator Cracking, Utility Patching	699	6
Rogers St	3	CDSRG03	10040	29th W	31st W	West Latonia	530.2	Satisfactory	Alligator Cracking	4025	6
Rogers St	6	CDSRG06	10008	33rd W	34th W	West Latonia	259.0	Satisfactory	Alligator Cracking, Utility Patching	2457	6
Rosedale Ct	1	CDSRD01	9773	Clifton	West End	Ritte's East Latonia	434.0	Satisfactory	Alligator Cracking	3299	6
Rosina Ave	2	CDSRS02	10981	Auburn	Hazel	West Latonia	288.3	Good	Alligator Cracking, Weathering	397	6
Rosina Ave	3	CDSRS03	10980	Hazel	Madison	West Latonia	268.7	Good	Alligator Cracking, Potholes, Weathering	2640	6
Rosina Ave	1	CDSRS01	10978	Southern	Auburn	West Latonia	1,410.1	Satisfactory	Alligator Cracking, Potholes	3732	6
Sehon St	1	CDSRH01	10945	28th W	Blackburn	West Latonia	231.3	Poor	Weathering, Block Cracking	805	6
Summit Dr	1	CDSSM01	10865	Myrtle	East End	West Latonia	516.7	Satisfactory	Alligator Cracking, Patching	4610	6
Summit Dr	1	CDSSM01	10865	Myrtle	East End	West Latonia	467.4	Satisfactory	Alligator Cracking, Patching	4611	6
Tibbatts St	1	CDSTB01	10896	Caroline	Southern	Ritte's East Latonia	421.8	Good	Patching, Alligator Cracking	1533	6
Tibbatts St	2	CDSTB02	10910	Southern	38th W	Ritte's East Latonia	107.9	Good	Alligator Cracking, Patching, Weathering	3401	6
Tracy Ave	1	CDSTC01	9866	South End	Earle	Ritte's East Latonia	404.4	Very Good	Alligator Cracking	2157	6
Tracy Ave	2	CDSTC02	9888	Earle	38th E	West Latonia	275.6	Very Good	Block Cracking	3705	6
Union St	1	CDSUN01	10002	Decoursey	33rd E	West Latonia	219.6	Good	Alligator Cracking, Weathering	558	6
Union St	1	CDSUN01	9993	Decoursey	33rd E	West Latonia	219.1	Good	Alligator Cracking, Weathering	2167	6
Vermont Ave	3	CDSVM03	10841	44th E	Baltimore	Latonia Rosedale	486.2	Poor	Alligator Cracking, Potholes, Depressions	3948	6
Vermont Ave	1	CDSVM01	9836	43rd E	Elmwood	Latonia Milldale	431.6	Very Good	Alligator Cracking	4187	6
Vermont Ave	2	CDSVM02	9837	Elmwood	44th E	West Latonia	328.7	Very Good	Utility Patching	4784	6
Victory Ave	1	CDSVC01	9775	46th E	South End	Ritte's East Latonia	830.2	Satisfactory	Weathering, Block Cracking	4677	6
Virginia Ave	1	CDSVG01	10845	45th E	South End	Ritte's East Latonia	464.4	Very Good	Block Cracking	3885	6
W 28th St	5	CDS2805	10947	Sehon	Decoursey	West Latonia	866.0	Poor	Potholes, Alligator Cracking, Rutting, Patching	780	6
W 28th St	3	CDS2803	10140	Alexandria	Melton	West Latonia	226.3	Good	Weathering, Alligator Cracking	2595	6
W 28th St	4	CDS2804	10946	Rogers	Sehon	West Latonia	315.9	Good	Alligator Cracking, Weathering	1354	6
W 28th St	1	CDS2801	10111	Latonia	Dakota	West Latonia	247.6	Satisfactory	Weathering	2663	6
W 28th St	2	CDS2802	10112	Dakota	Alexandria	West Latonia	242.9	Satisfactory	Weathering	3873	6
W 29th St	1	CDS2901	10039	Rogers	East End	West Latonia	172.2	Satisfactory	Weathering	1436	6
W 30th St	1	CDS3001	10937	Decoursey	West End	West Latonia	548.6	Poor	Weathering, Alligator Cracking, Potholes	3277	6
W 30th St	1	CDS3001	10942	Decoursey	West End	West Latonia	309.5	Poor	Weathering, Alligator Cracking, Potholes	7311	6
W 31st St	1	CDS3101	10022	Caroline	Rogers	West Latonia	486.4	Satisfactory	Block Cracking, Weathering	1973	6
W 31st St	2	CDS3102	10940	Rogers	Decoursey	West Latonia	307.4	Satisfactory	Edge Cracking	1529	6
W 31st St	2	CDS3102	10935	Rogers	Decoursey	West Latonia	210.7	Satisfactory	Edge Cracking	3502	6
W 31st St	2	CDS3102	10938	Rogers	Decoursey	West Latonia	295.8	Satisfactory	Edge Cracking	4024	6
W 32nd St	1	CDS3201	10090	West End	Latonia	West Latonia	175.3	Good	Weathering, Block Cracking	3636	6
W 32nd St	1	CDS3201	10095	West End	Latonia	West Latonia	158.4	Good	Weathering, Block Cracking	4299	6
W 32nd St	5	CDS3205	10017	Caroline	Rogers	West Latonia	495.0	Satisfactory	Alligator Cracking, Weathering	700	6
W 32nd St	6	CDS3206	10013	Rogers	Decoursey	West Latonia	212.1	Satisfactory	Weathering, Alligator Cracking	1453	6
W 32nd St	2	CDS3202	10088	Latonia	Watson	West Latonia	160.1	Satisfactory	Alligator Cracking, Weathering, Patching	4197	6
W 32nd St	2	CDS3202	10081	Latonia	Watson	West Latonia	157.1	Satisfactory	Alligator Cracking, Weathering, Patching	3094	6
W 32nd St	6	CDS3206	10009	Rogers	Decoursey	West Latonia	473.7	Satisfactory	Weathering, Alligator Cracking	3465	6
W 32nd St	3	CDS3203	10072	Watson	Southern	West Latonia	150.3	Satisfactory	Weathering	2344	6
W 32nd St	3	CDS3203	10065	Watson	Southern	West Latonia	97.1	Satisfactory	Weathering	3734	6
W 32nd St	4	CDS3204	10025	Graff	Caroline	West Latonia	384.6	Satisfactory	Alligator Cracking, Weathering	3872	6
W 33rd St	11	CDS3311	10007	Rogers	Decoursey	West Latonia	312.6	Poor	Joint Cracking, Potholes, Patching	698	6
W 33rd St	11	CDS3311	10000	Rogers	Decoursey	West Latonia	186.6	Poor	Joint Cracking, Potholes, Patching	3271	6
W 33rd St	2	CDS3302	10166	Cottage	Emerson	West Latonia	306.7	Satisfactory	Weathering, Alligator Cracking	2684	6
W 33rd St	5	CDS3305	10086	Latonia	Watson	West Latonia	156.1	Satisfactory	Joint Cracking, Weathering	4438	6
W 33rd St	3	CDS3303	10163	Emerson	Carlisle	West Latonia	151.7	Satisfactory	Joint Cracking, Weathering	4444	6

Street Name	Section ID	Unique ID	Road ID Number	From	To	Neighborhood	Length (Ft)	PCI	Defects	OBJECTID	CLASS
W 33rd St	1	CDS3301	10164	West End	Cottage	West Latonia	441.4	Satisfactory	Patching, Weathering	2223	6
W 33rd St	3	CDS3303	10159	Emerson	Carlisle	West Latonia	158.3	Satisfactory	Joint Cracking, Weathering	1983	6
W 33rd St	6	CDS3306	10064	Watson	Mabel	West Latonia	150.9	Satisfactory	Weathering, Block Cracking	2520	6
W 33rd St	6	CDS3306	10068	Watson	Mabel	West Latonia	152.9	Satisfactory	Weathering, Block Cracking	4209	6
W 33rd St	5	CDS3305	10079	Latonia	Watson	West Latonia	158.6	Satisfactory	Joint Cracking, Weathering	4036	6
W 33rd St	7	CDS3307	10059	Mabel	Grace	West Latonia	154.0	Satisfactory	Weathering, Alligator Cracking	2714	6
W 33rd St	4	CDS3304	10145	Carlise	Latonia	West Latonia	145.3	Satisfactory	Weathering	1531	6
W 33rd St	4	CDS3304	10123	Carlise	Latonia	West Latonia	164.0	Satisfactory	Weathering	1912	6
W 33rd St	7	CDS3307	10055	Mabel	Grace	West Latonia	152.0	Satisfactory	Weathering, Alligator Cracking	4140	6
W 33rd St	10	CDS3310	10016	Caroline	Rogers	West Latonia	494.2	Very Good	Weathering	2460	6
W 33rd St	9	CDS3309	10023	Graff	Caroline	West Latonia	394.5	Very Good	Utility Patching, Weathering	3660	6
W 33rd St	8	CDS3308	10021	West End	Graff	West Latonia	192.3	Very Good	Weathering	3714	6
W 34th St	2	CDS3402	10027	Graff	Caroline	West Latonia	391.7	Poor	Block Cracking, Weathering	2439	6
W 34th St	3	CDS3403	10014	Caroline	Rogers	West Latonia	492.0	Poor	Block Cracking, Weathering	3787	6
W 34th St	4	CDS3404	9989	Rogers	Decoursey	West Latonia	213.4	Good	Block Cracking, Weathering	2601	6
W 34th St	4	CDS3404	10005	Rogers	Decoursey	West Latonia	167.4	Good	Block Cracking, Weathering	3875	6
W 34th St	1	CDS3401	10032	Southern	Graff	West Latonia	558.4	Very Good	Weathering	7296	6
W 35th St	9	CDS3509	9986	Rogers	Decoursey	West Latonia	266.5	Poor	Alligator Cracking, Weathering, Potholes	2208	7
W 35th St	9	CDS3509	9990	Rogers	Decoursey	West Latonia	310.5	Poor	Alligator Cracking, Weathering, Potholes	3662	6
W 35th St	7	CDS3507	10035	Southern	Graff	West Latonia	290.0	Poor	Joint Cracking, Weathering	3098	6
W 35th St	4	CDS3504	10070	Watson	Mabel	West Latonia	153.5	Satisfactory	Patching, Weathering	335	6
W 35th St	3	CDS3503	10082	Latonia	Watson	West Latonia	161.2	Satisfactory	Patching, Block Cracking, Weathering	4446	6
W 35th St	4	CDS3504	10073	Watson	Mabel	West Latonia	149.2	Satisfactory	Patching, Weathering	1990	6
W 35th St	3	CDS3503	10084	Latonia	Watson	West Latonia	154.7	Satisfactory	Patching, Block Cracking, Weathering	3668	6
W 35th St	2	CDS3502	10147	Carlisle	Latonia	West Latonia	160.4	Very Good	Block Cracking, Weathering	345	6
W 35th St	2	CDS3502	10153	Carlisle	Latonia	West Latonia	154.0	Very Good	Block Cracking, Weathering	1660	6
W 35th St	5	CDS3505	10061	Mabel	Grace	West Latonia	151.4	Very Good	Weathering	1914	6
W 35th St	5	CDS3505	10057	Mabel	Grace	West Latonia	152.2	Very Good	Weathering	2902	6
W 35th St	6	CDS3506	10042	Grace	Eugenia	West Latonia	137.9	Very Good	Edge Cracking, Weathering	4039	6
W 35th St	1	CDS3501	10157	Emerson	Carlisle	West Latonia	154.0	Very Good	Weathering	440	6
W 35th St	1	CDS3501	10160	Emerson	Carlisle	West Latonia	153.7	Very Good	Weathering	3677	6
W 35th St	8	CDS3508	10030	Graff	East End	West Latonia	337.8	Very Good	Weathering	3537	6
W 36th St	4	CDS3604	9997	Decoursey	Caroline	West Latonia	339.3	Satisfactory	Block Cracking, Alligator Cracking	2338	6
W 36th St	4	CDS3604	9980	Decoursey	Caroline	West Latonia	186.7	Satisfactory	Block Cracking, Alligator Cracking	3480	6
W 36th St	5	CDS3605	10902	Caroline	Southern	West Latonia	357.7	Satisfactory	Joint Cracking, Block Cracking,	3839	6
W 38th St	2	CDS3802	10887	Tibbatts	Winston	West Latonia	353.4	Satisfactory	Alligator Cracking, Patching	339	6
W 38th St	1	CDS3801	10895	West End	Tibbatts	West Latonia	120.8	Satisfactory	Alligator Cracking, Patching	402	6
W 38th St	1	CDS3801	10903	West End	Tibbatts	West Latonia	246.7	Satisfactory	Alligator Cracking, Patching	1698	6
W 38th St	1	CDS3801	10909	West End	Tibbatts	West Latonia	242.0	Satisfactory	Alligator Cracking, Patching	1530	6
W 43rd St	2	CDS4302	10169	Boron	Winston	West Latonia	328.0	Satisfactory	Alligator Cracking, Block Cracking	2320	6
W 43rd St	1	CDS4301	10238	City Line	Boron	West Latonia	266.6	Satisfactory	Alligator Cracking, Block Cracking	3129	6
W 43rd St	1	CDS4301	10231	City Line	Boron	West Latonia	34.6	Satisfactory	Alligator Cracking, Block Cracking	3130	6
W 43rd St	2	CDS4302	10175	Boron	Winston	West Latonia	299.1	Satisfactory	Alligator Cracking, Block Cracking	3340	6
W 43rd St	2	CDS4302	10181	Boron	Winston	West Latonia	93.7	Satisfactory	Alligator Cracking, Block Cracking	3343	6
W 43rd St	1	CDS4301	9192	City Line	Boron	West Latonia	241.4	Satisfactory	Alligator Cracking, Block Cracking	3955	6
W 43rd St	2	CDS4302	10177	Boron	Winston	West Latonia	310.5	Satisfactory	Alligator Cracking, Block Cracking	4459	6
W 43rd St	2	CDS4302	10868	Boron	Winston	West Latonia	173.5	Satisfactory	Alligator Cracking, Block Cracking	4465	6
W 43rd St	1	CDS4301	10235	City Line	Boron	West Latonia	56.6	Satisfactory	Alligator Cracking, Block Cracking	8050	6
W Southern Ave	7	CDSSN07	10911	36th	Caroline	West Latonia	339.9	Poor	Alligator Cracking, Potholes, Patching	3402	6
W Southern Ave	7	CDSSN07	10890	36th	Caroline	West Latonia	38.2	Poor	Alligator Cracking, Potholes, Patching	3404	6

Street Name	Section ID	Unique ID	Road ID Number	From	To	Neighborhood	Length (Ft)	PCI	Defects	OBJECTID	CLASS
W Southern Ave	8	CDSSN08	10893	Caroline	Decoursey	West Latonia	136.7	Poor	Alligator Cracking, Potholes	3407	6
W Southern Ave	8	CDSSN08	9995	Caroline	Decoursey	West Latonia	280.8	Poor	Alligator Cracking, Potholes	4315	6
W Southern Ave	6	CDSSN06	10899	Railroad	36th	West Latonia	106.7	Poor	Alligator Cracking, Patching, Potholes	3840	6
W Southern Ave	1	CDSSN01	10099	Latonía	Ashland	West Latonia	184.4	Good	Alligator Cracking, Patching	224	6
W Southern Ave	1	CDSSN01	10076	Latonía	Ashland	West Latonia	208.2	Good	Alligator Cracking, Patching	1911	6
W Southern Ave	1	CDSSN01	10092	Latonía	Ashland	West Latonia	204.8	Good	Alligator Cracking, Patching	3479	6
W Southern Ave	5	CDSSN05	10033	34th W	35th W	West Latonia	437.5	Satisfactory	Potholes, Weathering	3099	6
W Southern Ave	2	CDSSN02	10078	Ashland	Rosina	West Latonia	97.6	Satisfactory	Alligator Cracking, Patching	3728	6
W Southern Ave	2	CDSSN02	10066	Ashland	Rosina	West Latonia	78.5	Satisfactory	Alligator Cracking, Patching	3730	6
W Southern Ave	2	CDSSN02	10060	Ashland	Rosina	West Latonia	180.8	Satisfactory	Alligator Cracking, Patching	3733	6
W Southern Ave	3	CDSSN03	10054	Rosina	Clifford	Ritte's East Latonia	171.1	Satisfactory	Joint Cracking, Alligator Cracking	2335	6
W Southern Ave	4	CDSSN04	10052	Clifford	34th W	West Latonia	267.7	Satisfactory	Alligator Cracking	2892	6
W Southern Ave	3	CDSSN03	10045	Rosina	Clifford	Ritte's East Latonia	191.2	Satisfactory	Joint Cracking, Alligator Cracking	3536	6
Watson Ave	3	CDSWT03	10074	33rd W	35th W	Ritte's East Latonia	411.2	Good	Alligator Cracking, Weathering	1991	6
Watson Ave	1	CDSWT01	10080	Southern	32nd W	Latonía Milldale	191.9	Good	Weathering, Patching	2345	6
Watson Ave	2	CDSWT02	10071	32nd W	33rd W	Latonía Milldale	408.9	Good	Alligator Cracking, Weathering	4210	6
Winchester St	2	CDSWC02	10921	33rd E	North End	Latonía Rosedale	1,362.4	Poor	Alligator Cracking, Potholes, Weathering	1433	6
Winchester St	1	CDSWC01	10924	34th E	33rd E	Latonía Rosedale	367.7	Satisfactory	Alligator Cracking, Weathering	4022	6
Windsor Ave	1	CDSWD01	9909	Glenn	Myrtle	Latonía Rosedale	311.7	Poor	Alligator Cracking, Potholes, Weathering	2221	6